



## EFFECTIVE IMMEDIATELY

### Notice of Product Withdrawal and Closeout

**Product:** 8300 TankGate and associated modules

**Manufacturer:** Varec, Inc.

**Overview:** The 8300 TankGate has been a long standing and reliable communications device that has supported the bulk liquid storage industry for over 15 years. Due to components obsolescence, the above listed product is being phased out. The impact is as follows:

**Repairs:** Please contact Varec for evaluation and possible repair upon removal of service.

**Successors:** The successor for the 8300TankGate is the 8810 RTU.

NEW MODEL	OLD MODEL
8810 Remote Terminal Unit 	8300 TankGate Interface 
Module 8814 - Serial	N83-032 Dual RS-485
Future Consideration	N83-036 Dual GSI ASCII
Module 8815 - Mark/Space	Module 83-101 - Mark/Space (Varec)
Future Consideration	Module 83-111 – Whessoe Bus Current Loop
Future Consideration	Module 83-112 – GPE Current Loop
Future Consideration	Module 83-120 - TRL/2 (SAAB)
Module 8812 - Bi Phase Mark	Module 83-140 - BPM (Enraf)
Summer 2020	Module 83-150- Tankway (L&J)
N/A	Module 83-161 - LON (Prime/Barton)
Future Consideration	Module 83-17x – Dual RS-232

#### Impact of this Closeout

##### Effective 6-May-2019

The 8300 TankGate and the following modules are impacted: 83-032, 83-036, 83-101, 83-111, 83-112, 83-120, 83-140, 83-150, 83-161, and 83-17x.

- Active quotes will be reviewed to ensure fulfillment can still be met.
- New quotes will be issued on a case-by-case basis dependent on current inventory levels. *Once the quote expiration date has passed, there is no guarantee orders will be accepted and fulfilled.*
- All existing warranties will be honored through the end of the specified warranty period.
- Firmware updates for the 8300 or any associated modules will only be available to support critical field issues. New functionality or enhancements will not be supported.

##### Effective 6-Nov-2019

Spare part orders for the 8300 TankGate and **any** modules will be accepted on a case-by-case basis. Fulfillment will be contingent on availability of specific components at the time of the order.

##### Effective 31-May-2020

Firmware updates for the 83xx series are no longer available.

##### Production Delivery Time

No change at this time.